

# C-620 – Miscellaneous Bulk Fiber



Miscellaneous bulk fibers are composed of numerous filaments gathered together and baled for bulk shipment. They are used for needed punch, stitched or hammer mill processes which can then be used in composite, acoustical or thermal insulation applications.

## General Product Specifications

### Product Information

Product	TP-40 Air Runback	TP-40 Beam Cutoff	TP-167 Uncut Forming	TP167 Cut Forming	TP-167 Thin Tube BY	TP-167 Uncut Thin Tube	TP-167 Start Up Bands
Binder	Starch	Starch	Starch	Starch	Starch	Starch	Starch
Moisture Content %	Max 0.1	Max 0.1	Max 13	Max 13	Max 13	Max 13	Max 13
Filament Diameter	Mixed	Mixed	Mixed	Mixed	Mixed	Mixed	Mixed

### Packaging Information


Approximate Pallet Weight - lb (kg)	1000 (453)	1700 (771)	1700 (771)	1700 (771)	1700 (771)	1700 (771)	1700 (771)
-------------------------------------	------------	------------	------------	------------	------------	------------	------------

Rev 2, 11/22/2016

# C-620 – Miscellaneous Bulk Fiber

## Nominal Packaging Dimensions

Description	Pallet	L-in (cm)	W-in (cm)	H-in (cm)
Misc. Bulk Fiber	Cardboard	54 (137.2)	36 (91.4)	33 +- 3* (83.8 +- 7.6)



## Storage, Shelf Life and Handling

### Storage and Shelf Life:

AGY recommends storing the materials in accordance with appropriate safety considerations, away from exposure to the elements and at 65-80F (18-27C) and 50-70% humidity. If the materials are stored under these conditions, they are stable, non reactive and will not degrade or exhibit negative characteristics for at least 3 years from the date of manufacture. Unused, unopened product older than this is likely still in good condition, however careful evaluation is recommended. Prior to use, pallets should be placed in the production area and any plastic wrap removed for a minimum of 24 hours to allow the material to acclimate to the processing environment. Special care should be given to pallets being moved from a cold environment into a warm, humid area as condensation may occur and this additional moisture can negatively impact the runability of the material, however, once the material has acclimated, this will no longer be an issue.

For product traceability reasons, the pallet label should be recorded or retained.

### Handling:

Fiberglass products process best if temperature and humidity are controlled, primarily because this will help to control the buildup of static electricity, fuzz and fly. AGY recommends that the material be run at 70 +/- 5 degrees F and 60 +/- 5% RH.

## Test Methods and Certificates

A copy of test methods and or a certificate of conformity may be issued upon request.

Chop product are chopped to exact specifications, and are free of contaminates such as clumps of fuzz and out of specification long chop. AGY accepts no responsibility for damaged material that shows any signs of physical abuse.

### AGY – World Headquarters / Americas

2556 Wagener Road  
Aiken, South Carolina, USA 29801  
Phone: +(1) 888.434.0945 (toll free)  
+(1) 803.643.1501  
Fax: +(1) 803.643.1180  
Email: asktheexpert@agy.com

### AGY – Europe

Le Gemellyon Nord  
57 Boulevard Marius Vivier Merle  
69003 Lyon, France  
Phone: +(33) 4727 81775  
Fax: +(33) 4727 81780

[www.agy.com](http://www.agy.com)

### AGY – Asia

Suite 1306-8, Bldg. 1,  
No. 1628 Jinshajiang Rd.  
Shanghai 200333 China  
Phone: +(86) 21 3251 3871  
Fax: +(86) 21 3251 2839